Quality Assurance Site Survey Report for Temecula (Lake Skinner)

Last updated April, 2012



AIRS Number	S Number ARB Number		Reporting Agency and Agency Code
060650016	33031	06/30/10	South Coast AQMD (061)

Site Address	County	Air Basin	Latitude	Longitude	Elevation
33700 Borel Rd. Winchester, CA 92596	Riverside	South Coast	33° 34' 59"N	117° 04' 20"W	453 m



Site Survey Report

Siting Information

Site Name: Temecula (Lake Skinner)	Date: 4/11/12	State Code: 33031	AIRS Number: 060650016		
Address: 33700 Borel Rd.	Latitude: 33° 34′ 59″	Longitude: 117° 04′ 20″	Elevation (m): 453 m		
Winchester, CA 92596	Senior AQIS: Keith Brown	Site Technician: Twyla Miner	Site Phone: N/A		
Operating Agency: South Coast AQMD					

General Siting Conditions

Station Temperature	Station Temperature Traffic		Predominant Wind Direction: SW	
Controlled: Yes	Description: Commercial	Site: Level	Arc Air Flow (Deg): 360	
Recorded: Yes	Distance: 10 m	Region: Rolling hills	Probe Last Cleaned: 5/12/11	
	Count (Veh/Day): 20	QA Manual	Manifold Clean: Yes	
Meteorology	Non-vehicular Local Sources	Approved: Yes	Cleaning Schedule: 6 months	
Located With Instruments: No	Description: none	Agency: South Coast AQMD	Auto calibrator Type: Environics 6103	
	Distance: 5	Urbanization: rural	Site Survey Complete: Yes	
	Direction:	Ground Cover: Asphalt / Gravel	Logbook Up To Date: Yes	

Action Items

Comments

Detailed Site Information

Temecula (Lake Skinner)				
060650016				
•				
	Sernardino-Ontario CA N	AS A		
		1071		
<u> </u>				
=				
Teledylic Al 1 400L				
532 S				
*	*			
			+	
			+	
			+	
			+	
1				
N/A	NI/A			
IN/A	IV/A			
N/Δ	N/Δ			
IV/A	IV/A			
N/A	N/A			
IV/A	IV/A			
N/A	N/A			
11/12	11/11			
Yes	Yes			
	-			
	-			
110				
N/A	N/A			
	= "			
	060650016 Latitude: 33° 34' 59' MWD Lake Skinner Pa 33700 Borel Rd. Win Riverside 10 m 20 Asphalt	December 20	Description	

Frequency of flow rate verification for manual PM samplers audit	N/A	N/A		
Frequency of flow rate verification for automated PM analyzers audit	N/A	Monthly		
Frequency of one- point QC check (gaseous)	Nightly	N/A		
Date of last annual performance evaluation	10/11/11	N/A		
Dates of semi-annual	N/A	06/02/11		
flow rate audits for PM monitors	N/A	11/30/11		
Date of past year's PM2.5-PEP audit	N/A	N/A		
Date of past year's Pb-PEP audit	N/A	N/A		

Temecula – Lake Skinner Site Photos



Looking North from probe



Looking East from the probe.



Looking South from the probe.



Looking West from the probe

Temecula – Lake Skinner Site Photos (Cont.)



Looking at the probe to the North.



Looking from the probe to the East.



Looking at the probe to the South.



Looking at the probe to the West.